

TDEC - Division of Water Resources

Chattanooga Field Office

ICIS NPDES Facilities Inspection Report

Bledsoe

						Fa	cility D	ata				Co		<u> </u>	
NPDES ID: TNR 117	2328		Facility	y Site N	lame	TALL	- Cont	cr 50	we	Projec	+	180	edsoe	_)	
				Add	tress	900	52-3			3		1		/	
Permit Eff. Date:			Perm	nit Exp	Date:		720 50				SIC	Code:			
				Co	mplia	ance M	1onitor	ing Info	orma	ation					
Compliance Monitor	ing Acti	vity Name	Stormwa	ter Cor	nstruct	ion Non	-Samplin	g							
		_					ove, selec	t the met	hod u	ısed:					
Compliance Monitoring Activity Compliance Monitoring Dates/Times															
		71 51 55		Cor	mpfia	ince M	lonitori	ng Dat	es/T	imes	WI S		Aufter VE.		
Entry Date/Time (mn	n/dd/yy	yy hh:mm):	11/30/	15						ı/dd/yyyy h	h:mm)	11/3	iolis		
					F.	acility	Repres	entativ	es		phoji				
On-Site Representative(s)Title, Phone Number Responsible Official(s), Title, Phone Number									2.0 9000						
ALTERNATION CONT.				5	Statute and Section Information										
Federal Statute: CWA - Clean Water Act					State Statute: Tennessee Wate							r Quality Control Act			
,		Stormwater													
Compliance A		-		om Ins	pection	on				1		7056	DUID		
Compliance Monitoring Agency Type: State					Agency Nai										
Did EPA assist/Inspection? No											\ <u></u>	Hours:			
Inspection Type: State					Compliance Monitoring Action Outcom							Not Immediately Corrected			
Lead Agency: If Joint Inspection, what was the purpose of the oth				<u></u>	Compliance Monitoring Rating Code:										
ir Joint Inspection, wi	nat was					Inchoc	tion (C	hack or	he +k	nose area	ic ava	luated)		S	
Permit		Aleas E	valuate				iance Pro		ny u	lose area		etreatme	nt	A Best E. L. N	
											Pollution Prevention				
Records / Records							Schedul	e							
Facility Site Review					Laboratory							Storm Water			
Effluent / Receiving Waters				Operations & Maintenance								Combined Sewer Overflow			
Flow Measurement					Sludge Handling / Disposal						Sa	Sanitary Sewer Overflow			
				Co	mpli	iance M	Monito	ring Su	mm	ary			11-5-51		
See 106															
				E	EPA a	ind Sta	te Rep	resenta	ative	es :	Tie a	J. A. A. T. S.			
Jason Dees		2_			DWR	/CHEFO	/634-570	4				11/	30/15		
Inspector's Signature					Agency / Office / Phone							Date			
Jennifer Innes					DWR/CHEFO/634-5719							19/1/15			
Manager's Signature)			Ager	ncy / Offi	ce / Phon	e				Date			

(Note: This form can only be printed to an XPS document, then saved for later use.)



TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION

Division of Water Resources

William R. Snodgrass Tennessee Tower, 312 Rosa L. Parks Avenue, 11th Floor, Nashville TN 37243 1-888-891-8332 (TDEC)

Compliance Inspection for General NPDES Permit for Stormwater Discharges from Construction Activities (CGP)

					_	_			T			
Site/Project Name: Tennessee Department of Corrections Taft Center (TDOC)								NPDES Tracking Number: Date Coverage was Issued			TNR112328	
Street Address or 000 SP 201								Start date:		as Issued	10-JAN-14 02-AUG-13	
Location: 900 SR-301								Estimated		to	31-DEC-13	
Site Replacement of the main sewer lines connecting all buildings on campus							Latitude (dd.dddd):			35.766111		
Description: to the existing pump station.							ampus	Longitude (-dd.dddd):			-85.2475	
									Acres Disturbed:			3.1
County(ies): Bledsoe EFO: Chattanooga MS4 Jurisdict										3,1		
_							Total Acre	s: 				
Nai	Name of Permittee (Developer/Operator): Tennessee Department of General Services											
Name of Official Contact: Matt Ingham Email: matt						@tn	ı.gov				Contact Pho	one: 423-532-7434
Address: 312 Rosa L. Parks Avenue City: Nashv										Zip: 37243		
Che	ck List (office & field checks)			Yes	T	No				Comme	nts	
1	Does the site have CGP cov	erage?		X								
2	Is NOC posted on site?					П						
3	Have the site contractors sig	gned the NOI?		1	T	Ħ						
4	Is the current SWPPP availa				T	Ħ						=
5	Are EPSCs in accordance w			╁⊨		Ħ						
6	Are EPSCs installed proper			1=	+	Ħ						
7	Are inspection reports avail			十一	+	Ħ						
8	Is the proper buffer zone ma			┿	+	Ħ						
	Were there unstable, inactive areas on the site? If so, does											
9	inspector know if length of	time has been more tha										
	(or 7 days for steep slopes)?											
10	Are more than 50 acres dist					Ш						
11	Has sediment discharged of	f site?										
12	Has sediment discharged int	to waters of the State?										
13	Are there unauthorized alter	rations to waters of the	State?									
Are there violations of an existing ARAP? If so, ARAP No.?												
15 Other pollutants/discharges or unusual problems?						П						
Project is complete and stable with no construction-related						$\overline{\Box}$						
stormwater discharges?												
General Comments: Work Appears complete from merical photography. Matthyhan confirmed project was complete. NOT requested												
_	Routine											
On-Site Contact (if available)												
On-Site Contact Name (Print): On-Site Contact Title:							:	Signature	e:			Date:
TDE	C Personnel/Information								EFO: Name a			
Inspector's Name (Print): Signature:						<u> </u>		Date: \ Time: \	130/15	Chattanooga Environmental Field Office 1301 Riverfront Parkway, Suite 206 Chattanooga, TN 37402		
	1500											

CN-1067 (Rev. 2-13)